



AutoAssure

Quality Auto Inspections

BIKE CHECK SHEET

Customer Details					Vehicle Details				
Name	Dharmendra		Email		Make	Honda		Chassis No.	7249720
Mobile			Address		Model	New Activa		Engine No.	249801
Physical Inspection					Manufacturing Year	2012		RTO Authority	
Over all Paint Condition					Colour	White		Fuel Type	Petrol
Excellent	Good	Satisfactory	Not ok	No. of Owners			Odometer Reading	21020/	
Fuel Tank	✓	Broken	Scratch	Leakage			Insurance Validity		
Front Wheel Mudguard	✓	Broken	Scratch	Not available	RC (Original Duplicate)	Original		Remark on RC	
Rear Wheel Mudguard	✓	Broken	Scratch	Not available	Engine				
Main Stand	✓	Broken	Scratch	Not available	Engine Noise	✓ Normal	Abnormal		
Ignition Switch	Ok	Broken	Missing	Not working	Engine Condition	✓ Clean	Leakage	Dirty	
Accessories					Smoke	White	Blue	Black	Colourless
Helmet	Available	Not Available	Damage	Pick Up	✓ Good	Not Good		Low	
Helmet Lock	Available	Not Available	Damage	Engine Starting	Good	Not Good		Battery Problem	
Chain Lock	Available	Not Available	Damage	Engine Oil Level	Ok	Not Ok		Very Low	
Seat Cover	Available	Not Available	Damage	Engine Oil Quality	Clean	Dirty		Medium	
Mirror Left	Available	Not Available	Damage	Brake					
Mirror Right	Available	Not Available	Damage	ABS	Available	Not Available			
Side Stand	Available	Not Available	Damage	Brake	Disc	Drum			
Saree Guard	Available	Not Available	Damage	Brake Padel Operation	Smooth	Hard	Not Working		
Others, if any				Brake Pad	Good	Medium	Bad		
Tyre					Brake Oil	Ok	Low	Empty	
Manufacturing Date	MM	YY	Tyre No.		Brake Padel Condition	Good	Not Good		
Front Tyre Life	0-20%	20-50%	50-80%	80+	Electrical				
Rear Tyre Life	0-20%	20-50%	50-80%	80+	Cut/Bubble				
Front Tyre	Good	Not Good	Broken	Bend	Battery Condition	Good	Not Good	Discharge / Dead	
Rear Tyre	Good	Not Good	Broken	Bend	Electrical Switches	Working	Not Working		
Front Rim	Good	Not Good	Broken	Bend	Spark Plug	Good	Bad		
Rear Rim	Good	Not Good	Broken	Bend	Electrical Wiring	Good	Minor Damage	Major damage	
Test Drive Experience					Head Lamp	Ok	Broken	Scratch	
Handle Bar Balance	Balanced	Not balanced	Major damage		Tail light	Ok	Broken		
Uneven Noise	Major	Minor	No		Indicator FR	Working	Broken	Not Working	
Uneven Vibrations	Major	Minor	No		Indicator FL	Working	Broken	Not Working	
Gear Shifting	Smooth	Noise	Damage		Indicator RR	Working	Broken	Not Working	
Clutch Operation	Smooth	Hard			Indicator RL	Working	Broken	Not Working	
Wheel Alingment	Ok	Not Ok			Odometer	Working	Cable Damage	Not Working	
Start & Stop	Single Attempt	Multiple Attempt	Not Starting		Evaluator Comments				
Kick Operation	Smooth	Not working	Servicing needed		Welding Job				
Brake Operation	Accurate	Loose	Setting required		Re-painted part				
Wheel Operation					Over all Performance	Good			
Front Wheel Bearings	Smooth	Minor Noise	Repair required		Recommendation for Warranty	Yes			
Rear Wheel Bearings	Smooth	Minor Noise	Repair required		Others				
Front Wheel Operation	Smooth	Minor Noise	Repair required						
Rear Wheel Bearings	Smooth	Minor Noise	Repair required						