



AutoAssure

Quality Auto Inspections

BIKE CHECK SHEET

Customer Details					Vehicle Details				
Name	Monika		Email		Make	Hero		Chassis No.	L15974
Mobile			Address		Model	Glamour		Engine No.	17346
					Manufacturing Year	2010		RTO Authority	
Physical Inspection					Colour	Black & Red		Fuel Type	Petrol
Over all Paint Condition	Excellent	Good	Satisfactory	Not ok	No. of Owners			Odometer Reading	15000/
Fuel Tank	✓	Broken	Scratch	Leakage	Insurance Validity			Insurance Type	
Front Wheel Mudguard	✓	Broken	Scratch	Not available	RC (Original Duplicate)			Remark on RC	
Rear Wheel Mudguard	✓	Broken	Scratch	Not available	Engine				
Main Stand	✓	Broken	Scratch	Not available	Engine Noise	✓ Normal	Abnormal		
Ignition Switch	Ok	Broken	Missing	Not working	Engine Condition	✓ Clean	Leakage		Dirty
Accessories					Smoke	White	Blue	Black	Colourless
Helmet	Available	Not Available	Damage		Pick Up	✓ Good	Not Good		Low
Helmet Lock	Available	Not Available	Damage		Engine Starting	Good	Not Good		Battery Problem
Chain Lock	Available	Not Available	Damage		Engine Oil Level	Ok	Not Ok		Very Low
Seat Cover	Available	Not Available	Damage		Engine Oil Quality	✓ Clean	Dirty		Medium
Mirror Left	Available	Not Available	Damage		Brake				
Mirror Right	Available	Not Available	Damage		ABS	Available			Not Available
Side Stand	✓ Available	Not Available	Damage		Brake	Disc			Drum
Saree Guard	Available	Not Available	Damage		Brake Padel Operation	Smooth	Hard		Not Working
Others, if any					Brake Pad	Good	Medium		Bad
Tyre					Brake Oil	Ok	Low		Empty
Manufacturing Date	MM	YY	Tyre No.		Brake Padel Condition	Good			Not Good
Front Tyre Life	0-20%	20-50%	50-80%	80+	Electrical				
Rear Tyre Life	0-20%	20-50%	50-80%	80+	Cut/Bubble				
Front Tyre	Good	Not Good	Broken	Bend	Battery Condition	Good	Not Good		Discharge/Dead
Rear Tyre	Good	Not Good	Broken	Bend	Electrical Switches	Working	Not Working		Rusted
Front Rim	Good	Not Good	Broken	Bend	Spark Plug	Good	Bad		Not Working
Rear Rim	Good	Not Good	Broken	Bend	Electrical Wiring	Good	Minor Damage		Major damage
Test Drive Experience					Head Lamp	Ok	Broken		Scratch
Handle Bar Balance	Balanced	Not balanced	Major damage		Tail light	Ok	Broken		Scratch
Uneven Noise	Major	Minor	No		Indicator FR	Working	Broken		Not Working
Uneven Vibrations	Major	Minor	No		Indicator FL	Working	Broken		Not Working
Gear Shifting	Smooth	Noise	Damage		Indicator RR	Working	Broken		Not Working
Clutch Operation	Smooth	Hard			Indicator RL	Working	Broken		Not Working
Wheel Alingment	Ok	Not Ok			Odometer	Working	Cable Damage		Not Working
Start & Stop	Single Attempt	Multiple Attempt	Not Starting		Evaluator Comments				
Kick Operation	Smooth	Not working	Servicing needed		Welding Job				
Brake Operation	Accurate	Loose	Setting required		Re-painted part				
					Over all Performance	Good			
Wheel Operation					Recommendation for Warranty	Yes			
Front Wheel Bearings	Smooth	Minor Noise	Repair required		Others				
Rear Wheel Bearings	Smooth	Minor Noise	Repair required						
Front Wheel Operation	Smooth	Minor Noise	Repair required						
Rear Wheel Bearings	Smooth	Minor Noise	Repair required						