



AutoAssure

Quality Auto Inspections

BIKE CHECK SHEET

Customer Details					Vehicle Details					
Name	Anju		Email		Make	TVS		Chassis No.	33367	
Mobile			Address		Model	PEP		Engine No.	731231	
					Manufacturing Year	2009		RTO Authority		
Physical Inspection					Colour	Pink		Fuel Type	Petrol	
Over all Paint Condition	Excellent	Good	Satisfactory	Not ok	No. of Owners			Odometer Reading	--	
Fuel Tank	✓	Broken	Scratch	Leakage	Insurance Validity			Insurance Type		
Front Wheel Mudguard	✓	Broken	Scratch	Not available	RC (Original Duplicate)			Remark on RC		
Rear Wheel Mudguard	✓	Broken	Scratch	Not available	Engine					
Main Stand	Ok	Broken	Scratch	Not available	Engine Noise	Normal	Abnormal			
Ignition Switch	Ok	Broken	Missing	Not working	Engine Condition	Clean	Leakage	Dirty		
Accessories					Smoke	White	Blue	Black	Colourless	
Helmet	Available	Not Available	Damage	Pick Up	Good	Not Good		Low		
Helmet Lock	Available	Not Available	Damage	Engine Starting	Good	Not Good		Battery Problem		
Chain Lock	Available	Not Available	Damage	Engine Oil Level	Ok	Not Ok		Very Low		
Seat Cover	Available	Not Available	Damage	Engine Oil Quality	Clean	Dirty		Medium		
Mirror Left	Available	Not Available	Damage	Brake						
Mirror Right	Available	Not Available	Damage	ABS	Available	Not Available				
Side Stand	Available	Not Available	Damage	Brake	Disc	Drum				
Saree Guard	Available	Not Available	Damage	Brake Padel Operation	Smooth	Hard	Not Working			
Others, If any					Brake Pad	Good	Medium	Bad		
Tyre					Brake Oil	Ok	Low	Empty		
Manufacturing Date	MM	YY	Tyre No.		Brake Padel Condition	Good	Not Good			
Front Tyre Life	0-20%	20-50%	50-80%	80+	Electrical					
Rear Tyre Life	0-20%	20-50%	50-80%	80+	Cut/Bubble	Battery Condition				
Front Tyre	Good	Not Good	Broken	Bend	Working	Not Working	Rusted			
Rear Tyre	Good	Not Good	Broken	Bend	Spark Plug	Good	Bad		Not Working	
Front Rim	Good	Not Good	Broken	Bend	Electrical Wiring	Good	Minor Damage		Major damage	
Rear Rim	Good	Not Good	Broken	Bend	Head Lamp	Ok	Broken		Scratch	
Test Drive Experience					Tail light	Ok	Broken			
Handle Bar Balance	Balanced	Not balanced	Major damage		Indicator FR	Working	Broken		Not Working	
Uneven Noise	Major	Minor	No		Indicator FL	Working	Broken		Not Working	
Uneven Vibrations	Major	Minor	No		Indicator RR	Working	Broken		Not Working	
Gear Shifting	Smooth	Noise	Damage		Indicator RL	Working	Broken		Not Working	
Clutch Operation	Smooth	Hard			Odometer	Working	Cable Damage		Not Working	
Wheel Alingment	Ok	Not Ok			Evaluator Comments					
Start & Stop	Single Attempt	Multiple Attempt	Not Starting		Welding Job					
Kick Operation	Smooth	Not working	Servicing needed		Re-painted part					
Brake Operation	Accurate	Loose	Setting required		Over all Performance	Good				
Wheel Operation					Recommendation for Warranty	Yes		Others		
Front Wheel Bearings	Smooth	Minor Noise	Repair required							
Rear Wheel Bearings	Smooth	Minor Noise	Repair required							
Front Wheel Operation	Smooth	Minor Noise	Repair required							
Rear Wheel Bearings	Smooth	Minor Noise	Repair required							